


KEB

3~ BDC

Forced Ventilation F



Pin	Wire	Winding	Signal
1	BK	U1	L1
2	BN	V1	L2
3	BU	W1	L3
⊖	GN-YE	GND	PE
	GN	U2	Y
	YE	V2	Y
	WH	W2	Y

